



Door Gap 3/4 x 4" Rule



This is a safety issue where some home elevators with swing-style landing doors have a hazard where it is possible for young children to get trapped between the landing door and the elevator cab gate.

TYPICAL ELEVATOR HOISTWAY



This is a code requirement in Florida. ASME ANSI A17.1-2019 National Safety Code for Elevators - Section 5.3 Private Residence Elevators as modified by various states.

5.3.1.7.2 Clearance Between Hoistway Doors and Landing Sills

The distance between the hoistway face of the hoistway doors and the hoistway edge of the landing sill shall not exceed 19 mm (0.75 in.) for swinging doors.

This only applies to homes with elevators that have swing-style landing doors.

PROPRIETARY AND CONFIDENTIAL

The information contained in this drawing is the sole property of Southeast Elevator. Any reproduction in part or as a whole without the written permission of Southeast Elevator is prohibited.



772-461-0030 | seelevator.com